Survey No. SM-371

yes X no

Maryland Historical Trust State Historic Sites Inventory Form

city, town

Magi No. 1903713604

DOE

state

Name (indicate preferred name) historic DAVIS HOUSE and/or common Location East side of Old Route 5, 1000 ft. north of street & number not for publication Charlotte Hall School Road clty, town Charlotte Hall ____ vicinity of congressional district state Maryland county St. Mary's Classification Category **Ownership Status Present Use** ___ district ___ public ___ occupied _ agriculture museum _ private ___ building(s) __ unoccupied _ commercial _ park ___ structure _ both __ work in progress _ educational _ private residence **Public Acquisition** _ site Accessible entertainment _ religious __ object _ in process _ yes: restricted government scientific _ being considered __ yes: unrestricted _ industrial _ transportation not applicable military no other: **Owner of Property** (give names and mailing addresses of all owners) Maryland Veterans Home Commission name Old Armory Building 11 Bladen Street telephone no.: street & number Annapolis state and zip code Maryland 21401 city, town **Location of Legal Description** courthouse, registry of deeds, etc. liber St. Mary's County Courthouse street & number folio city, town Leonardtown state Maryland Representation in Existing Historical Surveys title ⊿ate ____ state ___ county ___ local depository for survey records

7. Desc	ription	Survey No.	SM-371		
Condition excellent good fair	deteriorated ruins unexposed	Check one unaltered altered	Check one original site moved date of mo	ve	

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

7. Description

The Davis House stands on the east side of Old Route 5, approximately 1000 feet north of its intersection with Charlotte Hall School Road in Charlotte Hall.

The main section of the Davis House is two and one half stories tall and four bays wide with a cross gable roof. A three sided bay with a pyramidal roof extends from the south end of the west elevation. A boxed cornice runs along all four sides of the frame house and returns at each of the four gable ends. The house is sheathed with weatherboard siding, except for the attic story of the gable ends which are covered with diamond shaped wood shingles.

A one story screened porch with diagonal corners wraps around the west, north and south elevations and is supported by fluted Tuscan columns which taper at the top to a narrow capital. pedimented entrance portico with cornice returns is at the center of the west elevation of the porch.

The main entrance to the house is on the north end of the wes elevation. The door, with four horizontal panels, is framed by narrow sidelights and a transom. The windows on both the first and second stories have either 1/1 or 2/2 sash.

A two bay wide and three bay deep gable roofed wing extends from the east elevation. It also has a boxed cornice with returns on the gable end. There is a small entrance with a hood roof on the north elevation. A one bay wide and one bay deep gable roofed addition extends from the south-east corner of this wing. The addition is covered with asbestos siding and has 6/6 sash windows.

Another one story addition, one bay wide and one bay deep, with a metal shed roof, extends from the northeast corner of the wing. There is an entrance on the east elevation as well as a 6/6 sash window.

A one bay wide two story porch addition extends along the three northern bays of the two story wing. The first story is enclosed and is used as the kitchen. Each bay of the second story porch is marked by a turned post with jig sawn brackets.

<u>8. 5</u>	ignificance	Survey No. SM-371
	istoric archeology-pre -1499 archeology-his -1599 agriculture -1699 _X architecture	economics literature sculptureX education mllitary social/ engineering music humanitariar exploration/settlement philosophy theater
Specific	dates	Builder/Architect
check:	and/or Applicable Exception	a: _A _B X_C _D a: _A _B _C _D _E _F _G ae: national state X local
Prepare		graph of significance and a general statement of history and
support		, vi

The land on which the Davis house stands was in the hands of the Kilgour family for most of the nineteenth century. William Kilgour's will of July 3]

]796 mentions land "at the Cool Springs" which he bought from Zachariah Billinsley and Benjamin Ogden. The land, probably still undeveloped, was subdivided and sold by Matthew Kilgour in the]860's. The Davis family sold the property, along with the house, to the Trustees of Charlotte Hall School. The house was acquired by the Board Public Works in]978 and razed in]984.

This house is of no architectural signifigance.

9. Major Bibliographical References

Survey No. SM-371

Land Records St. Mary's County

10. Geogra	phical Data			
Quadrangle name Char	operty <u>less than one</u> lotte Hall OT complete UTM reference		Quadrangle scale	
Zone Easting	Northing	B Zone Eas	sting Northing	
C		□		
Verbal boundary desc	ription and justification			
List all states and cou state	inties for properties overlap code	county	y boundaries code	
state	code	county	code	
11. Form P	repared By			
name/title ^G eoffrey H	lenry			
organization Mary 1	and Historical Trus	t date	4/85	
Shaw	House, 21 State Ci	rcle telepho	269-2438 one	-
Ar	napolis	state	Maryland 21401	

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 supplement.

The survey and inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

return to:

Maryland Historical Trust

Shaw House

21 State Circle


Annapolis, Maryland 21401

(301) 269-2438


7. Description (Continued)


In the interior, there is a narrow entrance hall, with stairs leading to the second floor rising from the left hand side. The two largest rooms are to the right of the hallway and are linked by a paneled sliding door. There is a fireplace on the south wall of the first room flanked by large window seats. Most of the rooms on the first floor have closets or cupboards. The door and window trim is late nineteenth century, usually with bullsege corner blocks. The rooms in the various additions on the east side of the house have plain trim as well as dropped ceilings of asbestos panels.

The second floor consists of four bedrooms, a bathroom, a kitchen and the porch. The window and door trim are identical to that on the first floor, but most of the walls are covered with thin plywood board and all have dropped asbestos ceilings.



Scale |11=101







SM-371 Davis House Charlotte Hall, Md. Porch on north facade



SM-371 Davis House Charlotte Hall, Md. North Facade



Davis House Charlotte Hall, Md. Detail of porch on west facade

SM-371



SM-371 Davis House Charlotte Hall, Md. West Facade



SM-371
Davis House
Charlotte Hall, Md.
Southwest elevation
Geoffrey Henry
Negatives at MHT

7/84



SM-371
Davis House
Charlotte Hall, Md.
South elevation
Geoffrey Henry
Negatives at MHT

7/84



SM-371
Davis House
Charlotte Hall, Md.
South elevation
Geoffrey Henry
Negatives at MHT

7/84



SM-371 Davis House Charlotte Hall, Md. SE Corner